

September 2015

9xx Series Cameras Firmware

General Description

Vicon has released the latest firmware for a list of 9xx series of cameras. The accompanying Smart Manager discovery tool version 2.3.3.3 does not change. It is important to remember that when these cameras are used, ViconNet version should be minimum 6.6.71 (SP2).

The updated firmware is as follows:

Camera	Older Firmware	Newest Firmware
V920D and V921D, V921B, V922B	T4_V2.2.4	T4_V2.3.1
V922D, V923D, V-CELL-HD, V923B, CE202D-N and CE202D- WNPT	T6_V1.9.9	T6_V2.0.6
CE102D-NIR and CE102B-NIR	T8_V1.4.3	T8_V1.5.8

Vicon Production

The latest firmware and discovery tool are available on Vicon's web site. A link is provided in the installation section of this document. Production will switch over to the new firmware for new cameras.

Vicon Strongly recommends updating the cameras to this firmware to receive the most stable and secured solution.



Firmware Updates

ONVIF and web service lock up

In some cases, camera that had multiple clients polling events from the cameras caused the camera ONVIF and web services to lock up resulting in a communication error message when trying to access the camera. This has been addressed. Reports of lockup on extreme load are still under investigation.

Day / Night Switching and VMD

Added a delay following a switch from day to night mode or back so the switch won't trigger a VMD alarm.

Installing the Updated Firmware

The latest firmware is available on Vicon's website from the Support tab – Technical Support – Software Downloads – Vicon Network Camera Software; a link is provided below.

http://www.vicon-security.com/support-technical-support-software-downloads-network-cameras.htm

System

Sectordigutation

<

Download the firmware to your PC. Go to the camera's Maintenance screen.





Go to the Upgrade section and use the Browse button to locate the firmware on your PC. Press the Upgrade button. During the upgrade process, so not turn off the power to the camera. Wait at least 5 minutes and access the camera again. The new firmware should be installed. This can be checked from the Basic Configuration screen.

